

Jabra Table Stand

Overview










Table Stand and cable organizer

Cable organizer lids


Screws

			
M3x12mm	M5x6mm (short)	M5x9mm (medium)	M5x12mm (long)
Screws for the front and back cable organizer lids	Screws for the PanaCast 50 VBS PanaCast 55 VBS	Screws for the PanaCast 40 VBS PanaCast U30	Screws for the PanaCast 50

Tools needed




4mm hex key
(included with
PanaCast 50 VBS)



Screwdriver
Torx T10 and T25
(not included)


Jabra Table Stand

PanaCast 50



1



Tilt the hinge on the PanaCast 50 for easy access to the screw holes.



2


Screw the PanaCast 50 to the Table Stand using the using the supplied long screws (**M5x12mm**).

M5x12



3

Connect the power, Ethernet and USB-C cables to the video bar.





4


Pass the power and Ethernet cables through the table stand and place them on the back cable organizer.

Use the front cable organizer to place the USB-C cable.

Screw the cable organizer lids to the table stand using the **M3 x12mm** screws.


M3x12

- 5 Rotate the video bar into its final position and angle the camera to point at eye-level.



Jabra Table Stand


PanaCast 50 VBS



1


Attach the video bar mount to the table stand using the supplied short screws (**M5x6mm**).

M5x6




2

Attach the video bar to the video bar mount.
Screws are not required.



3

Rotate the video bar down for easy access to the ports. Connect the power, Ethernet, HDMI and USB-C cables to the video bar.





4


Pass the power, Ethernet and HDMI cables through the table stand and place them on the back cable organizer.

Use the front cable organizers to place the HDMI cable (wired content sharing), USB-C cable (BYOD) or USB cable for input devices (keyboard and/or mouse).


Screw the cable organizer lids to the table stand using the **M3x12mm** screws.

M3x12

- 5 Screw the cable cover to the video bar using the supplied screws and hex key.




- 6 Rotate the video bar into its final position and angle the camera to point at eye-level.



Jabra Table Stand


PanaCast 55 VBS



1


Attach the video bar mount to the table stand using the supplied short screws (**M5x6mm**).

M5x6




2

Attach the video bar to the video bar mount.
Screws are not required.



3

Rotate the video bar down for easy access to the ports. Connect the power, Ethernet, HDMI and USB-C cables to the video bar.




4


Pass the power, Ethernet and HDMI cables through the table stand and place them on the back cable organizer.

Use the front cable organizers to place the HDMI cable (wired content sharing), USB-C cable (BYOD) or USB cable for input devices (USB mouse).


Screw the cable organizer lids to the table stand using the **M3x12mm** screws.

M3x12

- 5 Screw the cable compartment cover to the video bar.




- 6 Rotate the video bar into its final position and angle the camera to point at eye-level.



Jabra Table Stand



PanaCast 40 VBS



1


Screw the video bar to the table stand using the supplied medium screws (**M5x9mm**).

M5x9




2

Connect the power, Ethernet, HDMI and USB-C cables to the video bar.



3

Screw the **cable compartment cover** to the video bar. Rotate the video bar up.





4

Pass the power, Ethernet and HDMI cables through the table stand and place them on the back cable organizer.


Use the front cable organizers to place the HDMI cable (wired content sharing), USB-C cable (BYOD) or USB cable for input device (keyboard or mouse).

Screw the cable organizer lids to the table stand using the **M3 x12mm** screws.

M3x12


5

Adjust the video bar into its final position and angle the camera to point at eye-level.



Jabra Table Stand



PanaCast U30



1


Screw the video bar to the table stand using the supplied medium screws (**M5x9mm**).

M5x9




2

Connect the power, Ethernet, HDMI and USB-C cables to the video bar.



3

Screw the **cable compartment cover** to the video bar. Rotate the video bar up.





4

Pass the power, Ethernet and HDMI cables through the table stand and place them on the back cable organizer.

Use the front cable organizers to place the HDMI cable (wired content sharing), USB-C cable (BYOD) or USB cable for input device (keyboard or mouse).

Screw the cable organizer lids to the table stand using the **M3 x12mm** screws.

M3x12

5

Adjust the video bar into its final position and angle the camera to point at eye-level.

